BioStation 3 Max

RELEASE NOTES

Version 1.1.0

English
EN 301.00.BS3M

suprema
SECURITY & BIOMETRICS

CONTENTS

Firmware Version 1.1.0

Firmware Version 1.0.1

Firmware Version 1.0.0

Firmware Version 1.1.0 (Build No. 1.1.0_260922)

Release | 2026-09-23

New Features and Improvements

1. Added support for video playback on the standby screen.

   > This feature can be configured in BioStar X. For detailed instructions, refer to Devcie Settings → Advanced Settings in the BioStar X guide.

2. Supported EV2 Secure Messaging authentication and issuance for DESFire EV2 and EV3 cards.
3. Improved OSDP reader mode to display "Access Denied" when access is denied by a third-party control panel.
4. Improved BLE stability.
5. Expanded allowed characters for User ID and User Name
   - Added support for periods (.) in User ID
   - Added support for periods (.) and apostrophes (') in User Name
6. Improved T&A message display to show on two lines.
7. Improved Fire alarm zone status display and alarm clearing behavior after power restart following a fire alarm.

Bug Fixes

1. Video streaming stopping after a certain period when connecting to RTSP over TCP. Affects version: 1.0.0
2. Devices that do not support the buzzer failing to connect when integrated with an OSDP panel. Affects version: 1.0.0
3. Card authentication failure on connected Wiegand readers. Affects version: 1.0.0
4. Device freezing or rebooting when face authentication occurs while adding or deleting users. Affects version: 1.0.0
5. Device freezing or rebooting and delayed user enrollment during user synchronization. Affects version: 1.0.0
6. LED effect not working when the screen saver is active. Affects version: 1.0.0
7. Invalid values being accepted in the device's Ethernet settings. Affects version: 1.0.0
8. Improved icon display issues on the master device screen under certain conditions Affects version: 1.0.0

- Lock icon disappearing when authentication succeeds at another door while in **Manual Lock** state
- Lock icon not displayed on the master device screen while in **Manual Lock** state
- Door icon disappearing on the master device screen when adding a door configuration

9. Video not displayed on the receiving device during a VoIP call. Affects version: 1.0.0
10. Fingerprint scan screen appearing when enrolling a fingerprint during a VoIP call. Affects version: 1.0.0
11. Date and time displayed incorrectly in the event log when the **Time Zone** is set to UTC-1 through UTC-12. Affects version: 1.0.0
12. Incorrect guidance message displayed when enrolling or editing a fingerprint. Affects version: 1.0.0
13. Suprema Mobile Access authentication failing on certain Android devices. Affects version: 1.0.0
14. Face authentication failing in bright external lighting conditions. Affects version: 1.0.0
15. Master device's IR LED blinking when scanning a fingerprint on a slave device. Affects version: 1.0.0
16. Reboot occurring when changing the fingerprint template format on standard models. Affects version: 1.0.0
17. **Lock Override** card authentication not working on a door created with a Wiegand reader when the reader is disabled. Affects version: 1.0.0

Firmware Version 1.0.1 (Build No. 1.0.1_260623)

Release | 2026-06-24

Bug Fixes

1. The fingerprint sensor LED remaining on continuously and failing to turn off. Affects version: 1.0.0

Firmware Version 1.0.0 (Build No. 1.0.0_260415)

Release | 2026-05-15

Initial Firmware Developed.

Suprema Inc.

17F Parkview Tower, 248, Jeongjail-ro, Bundang-gu, Seongnam-si, Gyeonggi-do, 13554, Rep. of KOREA

Tel: +82 31 783 4502 | Fax: +82 31 783 4503 | Inquiry: sales_sys@supremainc.com

For more information about Suprema's global branch offices,
visit the webpage below by scanning the QR code.
https://supremainc.com/en/about/global-office.asp

© 2026 Suprema Inc. Suprema and identifying product names and numbers herein are registered trade marks of Suprema, Inc.
All non-Suprema brands and product names are trademarks or registered trademarks of their respective companies.
Product appearance, build status and/or specifications are subject to change without notice.