Door Module

RELEASE NOTES

Version 1.2.2

English

EN 301.00.DM20

suprema

SECURITY & BIOMETRICS

CONTENTS

- Firmware Version 1.2.2
- Firmware Version 1.2.1
- Firmware Version 1.2.0
- Firmware Version 1.1.5
- Firmware Version 1.1.4
- Firmware Version 1.1.3
- Firmware Version 1.1.2
- Firmware Version 1.0.15
- Firmware Version 1.0.14
- Firmware Version 1.0.13
- Firmware Version 1.0.0

Firmware Version 1.2.2 (Build No. 1.2.2_220103)

Release | 2022-01-05

New Features and Improvements

1. Improvements related to RS-485 communication.

Firmware Version 1.2.1 (Build No. 1.2.1_210323)

Release | 2021-03-29

New Features and Improvements

1. Improved that the Wiegand input signal is correctly transmitted regardless of the hardware version.
    - The inverted Wiegand input signal was made due to the Weigand circuit change.

Firmware Version 1.2.0 (Build No. 1.2.0_200604)

Release | 2020-06-05

New Features and Improvements

1. Added feature to change device ID.

Bug Fixes

1. Mac error occurs when RS-485 communication does not comply with OSDP standard.

Firmware Version 1.1.5 (Build No. 1.1.5_190306)

Release | 2019-06-14

Bug Fix

1. An authentication failure error occurs if setting the Wiegand format to 256 bit when XPass D2 is connected as Wiegand reader.

Firmware Version 1.1.4 (Build No. 1.1.4_181031)

Release | 2018-11-28

New Features and Improvements

1. When there is the response data with OSDP Secure Session, it responds with 0x16 for SEC_BLK_TYPE value and responds with 0x18 when there is no data.

Firmware Version 1.1.3 (Build No. 1.1.3_171229)

Release | 2018-04-13

New Features and Improvements

1. When there is the response data with OSDP Secure Session, it responds with 0x16 for SEC_BLK_TYPE value and responds with 0x18 when there is no data.
2. Verified OSDP compatibility with the latest version of the master device.
    - FS2 AWB/D (V1.1.0)
    - BSA2-OEPW/OHPW/OIPW/OMPW (V1.5.0)
    - BS2-OEPW/OHPW/OIPW/OMPW (V1.6.0)
    - CS40 (V1.1.0)
    - BEW2-OAP/ODP/OHP/OAP(UL) (V1.2.0)
    - BSL2-OE/OM (V1.3.0)
    - BEP2-OA/OD/ODS (V1.1.0)

Firmware Version 1.1.2 (Build No. 1.1.2_170103)

Release | 2017-02-13

New Features and Improvements

1. OSDP
    - Add two Manufacturer Specific Command (MFG_RELAY_ON and MFG_RELAY_OFF)
    - Support Release Alarm
    - Add ability to change Secure Key in Secure Session

Firmware Version 1.0.15 (Build No. 1.0.15_160429)

Release | 2016-12-08

Bug Fixes

1. Communication is not possible when encountered a packet size exceeding the maximum OSDP packet queue.

Firmware Version 1.0.14 (Build No. 1.0.14_160111)

Release | 2016-01-19

Bug Fixes

1. OSDP ID is changed to zero and communication is not possible if FW upgrade is performed when connecting to BioStation 2 or BioStation A2 as a slave device.

Firmware Version 1.0.13 (Build No. 1.0.13_150810)

Release | 2015-08-10

New Features and Improvements

1. Output the NACK signal when SecuBlock error occurs.
2. Change Wiegand Input Interval Time
3. Reset the setting values of Supervised Input when press INIT button

Bug Fixes

1. Displays incorrect port number when Supervised Input port is grounded several times.

Firmware Version 1.0.0 (Build No.1.0.0_150130)

Release | 2015-01-30

Initial firmware developed.

Suprema Inc.

17F Parkview Tower, 248, Jeongjail-ro, Bundang-gu, Seongnam-si, Gyeonggi-do, 13554, Rep. of KOREA

Tel: +82 31 783 4502 | Fax: +82 31 783 4503 | Inquiry: sales_sys@supremainc.com

For more information about Suprema's global branch offices,
visit the webpage below by scanning the QR code.
https://supremainc.com/en/about/global-office.asp

© 2026 Suprema Inc. Suprema and identifying product names and numbers herein are registered trade marks of Suprema, Inc.
All non-Suprema brands and product names are trademarks or registered trademarks of their respective companies.
Product appearance, build status and/or specifications are subject to change without notice.