Output Module

RELEASE NOTES

Version 1.2.1

English

EN 301.00.OM-120

suprema

SECURITY & BIOMETRICS

CONTENTS

- Firmware Version 1.2.1
- Firmware Version 1.2.0
- Firmware Version 1.1.0
- Firmware Version 1.0.0

Firmware Version 1.2.1 (Build No.1.2.1_220103)

Release | 2022-01-05

New Features and Improvements

1. Improvements related to RS-485 communication.

Bug Fixes

1. The door relay did not operate according to the input status due to a relay 6-11 port order error. Affects version: 1.0.0

Firmware Version 1.2.0 (Build No.1.2.0_200624)

Release | 2020-07-09

New Features and Improvements

1. Added feature to change device ID.

Bug Fixes

1. Mac error occurs when RS-485 communication does not comply with OSDP standard.

Firmware Version 1.1.0 (Build No.1.1.0_181031)

Release | 2018-11-26

New Features and Improvements

1. If the data transmission fails when communicating with OSDP, it is transmitted again.
2. The OSDP ID command does not respond if a user changes the OSDP key using Secure I/O 2.

Firmware Version 1.0.0 (Build No.1.0.0_170103)

Release | 2017-01-03

Initial firmware developed.

Suprema Inc.

17F Parkview Tower, 248, Jeongjail-ro, Bundang-gu, Seongnam-si, Gyeonggi-do, 13554, Rep. of KOREA

Tel: +82 31 783 4502 | Fax: +82 31 783 4503 | Inquiry: sales_sys@supremainc.com

For more information about Suprema's global branch offices,
visit the webpage below by scanning the QR code.
https://supremainc.com/en/about/global-office.asp

© 2026 Suprema Inc. Suprema and identifying product names and numbers herein are registered trade marks of Suprema, Inc.
All non-Suprema brands and product names are trademarks or registered trademarks of their respective companies.
Product appearance, build status and/or specifications are subject to change without notice.