XPass S2

RELEASE NOTES

Version 2.4.4

English

EN 301.00.XPS2

suprema

SECURITY & BIOMETRICS

CONTENTS

- Firmware Version 2.4.4
- Firmware Version 2.4.3
- Firmware Version 2.4.2
- Firmware Version 2.4.1
- Firmware Version 2.4.0
- Firmware Version 2.3.1
- Firmware Version 2.3.0
- Firmware Version 2.2.6
- Firmware Version 2.2.5
- Firmware Version 2.2.3
- Firmware Version 2.2.1
- Firmware Version 2.2.0
- Firmware Version 2.1.3
- Firmware Version 2.1.2
- Firmware Version 2.0.2

Firmware Version 2.4.4 (Build No. 2.4.4_180724)

Release | 2018-09-04

Bug Fixes

1. When formatting MIFARE Plus card to use it as a smart card, the site key of the card gets written differently than the value set on the device.
2. When using as a slave device, the RS-485 connection gets disconnected after changing the device settings and restarting the device.
3. Trigger & Action does not work normally when Bypass mode is set in Wiegand output.
4. Device ID changes to zero and does not work normally.
5. The device fails to boot because the secure chip authentication failed repeatedly.
6. The device cannot receive an IP address from the DHCP server in a specific environment.

Firmware Version 2.4.3 (Build No. 2.4.3_170724)

Release | 2017-07-25

Bug Fixes

1. Issue where the device is malfunctioned when device log is full.
2. Issue where the device is malfunctioned when receiving or sending Wiegand signals.

Firmware Version 2.4.2 (Build No. 2.4.2_170420)

Release | 2017-04-27

Bug Fixes

1. Issue with Device ID changes to zero.

Firmware Version 2.4.1 (Build No. 2.4.1_170217)

Release | 2017-02-20

Bug Fixes

1. Issue where the device reboots when the FW upgrade has not been completed.

Firmware Version 2.4.0 (Build No. 2.4.0_170202)

Release | 2017-02-06

New Features and Improvements

1. Support elevator control.
2. Support for alphanumeric ID.

Firmware Version 2.3.1 (Build No. 2.3.1_160921)

Release | 2016-09-22

Bug Fixes

1. Memory leak issue when a T&A device is registered as a slave device and users authenticate after pressing a T&A key.
2. Issue where the master device reboots when a device with an old firmware version is connected as a slave device and a user authenticates with a card on the slave device.

Firmware Version 2.3.0 (Build No. 2.3.0_160704)

Release | 2016-09-07

New Features and Improvements

1. Support for multi-Wiegand format input/output.

Bug Fixes

1. Issue where a faulty acceptance event would occur when restarting the device after a fingerprint authentication success event.
2. Delay in card authentication success.

Firmware Version 2.2.6 (Build No. 2.2.6_160509)

Release | 2016-05-09

Bug Fixes

1. Issue where the door lock would not work properly if the relay was set on the device menu.

Firmware Version 2.2.5 (Build No. 2.2.5_160408)

Release | 2016-04-08

Bug Fixes

1. Issue where the device would restart when upgrading from a firmware before version 2.2.0.

Firmware Version 2.2.3 (Build No. 2.2.3_160204)

Release | 2016-02-04

New Features and Improvements

1. The stability of the network communication (RS-485) has been improved.

Bug Fixes

1. Issue with door relay operation.
2. Issue with alarm lasting time.

Firmware Version 2.2.1 (Build No. 2.2.1_160119)

Release | 2016-01-19

Bug Fixes

1. Port for server mode.
2. Intermittent disconnection with BioStar 2.

Firmware Version 2.2.0 (Build No. 2.2.0_160107)

Release | 2016-01-07

New Features and Improvements

1. Support for scheduled lock / unlock zone.
2. Support for global anti-passback zone.

Bug Fixes

1. Door relay not operating properly after a device restart.

Firmware Version 2.1.3 (Build No. 2.1.3_150908)

Release | 2015-09-09

Bug Fixes

1. Door relay not operating properly after a device restart.

Firmware Version 2.1.2 (Build No. 2.1.2_150819)

Release | 2015-08-19

New Features and Improvements

1. Support for DM-20 and third-party Wiegand reader connection.
2. Support for anti-passback zone.
3. Support for fire alarm zone.

Firmware Version 2.0.2 (Build No. 2.0.2_150222)

Release | 2015-02-22

Initial firmware developed.

Suprema Inc.

17F Parkview Tower, 248, Jeongjail-ro, Bundang-gu, Seongnam-si, Gyeonggi-do, 13554, Rep. of KOREA

Tel: +82 31 783 4502 | Fax: +82 31 783 4503 | Inquiry: sales_sys@supremainc.com

For more information about Suprema's global branch offices,
visit the webpage below by scanning the QR code.
https://supremainc.com/en/about/global-office.asp

© 2026 Suprema Inc. Suprema and identifying product names and numbers herein are registered trade marks of Suprema, Inc.
All non-Suprema brands and product names are trademarks or registered trademarks of their respective companies.
Product appearance, build status and/or specifications are subject to change without notice.